

FIG. 1




FIG. 1

FIG. 2




FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B




FIG. 5




FIG. 6A





FIG. 6B



VEHICLE BODY END PORTION

FIG. 7




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 8D






FIG. 9




FIG. 10A




FIG. 10B




FIG. 10A

FIG. 11




FIG. 12





FIG. 13



52

A

53

54

55

56 a

56 b

56 c

57

BUMPER OF MOTOR VEHICLE

FIG. 15B RELATED ART

